




Error Analysis Process Description for CP Controller

Light and Basic Charging systems





Error pattern: Locking pin not fully inserted

The error can be identified quickly, if you open the hinged lid or the swivel lid on the socket.

Please shine a torch into into the socket.

If you can see that the lock pin at the top is not completely inserted (Figure 2), it must be reset manually.

Please release the red lever (Figure 3), which is fastened in the charging system with a cable tie.

The lever is mounted from behind on the actuator (Figure 4 + 5), which is installed on the socket.

Turn the red lever clockwise to the stop.

Check whether the locking pin can no longer be seen.

Then please detach the lever from the actuator and fasten it in the housing.

This error can be caused, through improper handling (e.g. jerky pulling of the charging plug when charging).

However, if this error repeatedly occurs, contact the MENNEKES eMobility service number (Tel. +49 (0) 27 23 / 41-600).

